

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
(Re: G.O.Ms. 2070/PWD/Dt. 23-01-1970)

- 1 Name of the Officer : DHANYA R
- 2 Name of the School : Ansa English School Kolamba
- 3 Location with name of Education District / sub-District : Tirur Edappal - Sub Dist
- 4 Classification of Building as specified in column 4 of the application for fitness certification and size :  
As per Application  
RCC Building  
GF: 6.10 x 6.10 x 3.60 - 6 class rooms  
FF: 6.10 x 6.10 x 3.60 - 6 class rooms
- 5 Period for which the certificate is issued : 2023 - 2024 Academic year
- 6 Nature of defects, if any :
  - a) Foundation and basement : }
  - b) Superstructure : NIL
  - c) Door and Windows : }
  - d) Wood work wrought and put up : }
  - e) Roof : }
  - f) Flooring : }
  - g) Miscellaneous (Crack etc.) : }
- 7 Any major defects noticed which will render the building unsafe in any manner : NIL
- 8 Whether maintenance work have been done properly : Yes
- 9 Whether the structure is sound or not for conducting classes : Structure is sound under normal cond of weather conditions


**Note:** 1. The stability of the structure should be examined also with reference to location, altitude intensity of wind exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate

## CERTIFICATE

Certified that the school building was inspected by me on 29/05/2023 and found to be fit/unfit to conduct classes for the period 2023-2024 academic year for the reasons stated above.

place: Edappal  
Date: 28/05/2023



  
 Assistant Engineer  
 LID & EW (LSGD) section  
 Edappal Gramapanchayath  
 Pin: 679576